
Schematic Diagram for the 1978 Airheads

As copied from Owner's Handbook

Schem1978.htm-38D

This schematic should be copied to YOUR computer, and then expanded to the size you need. The resolution of this JPG is high enough to enable a considerable zoom/expansion, and then printing if you so desire.



Key to wiring diagram

BMW R 60/7 - R 100 S


- 1 Turn indicator switch with starter button and k switch 2 Headlight a) Flasher unit b) High beam c) Low beam d) Parking light e) Light relay f) Ignition/light switch g) Contact plate with fuses 3 Main light control switch with dimmer switch, high beam flasher and horn button 4 Front right turn indicator 5 plug, 2-pole 1 Turn indicator switch with starter button and kill

- Fold right (unit indicato is plug, 2-pole
 Clutch operated switch
 Voltmeter (R 100 S only)
 Front left turn indicator
 Horn
 Horn 9 Front left turn indicator
 10 Horn
 11 Hyd operated front brake stop switch
 12 Combined Instrument

 a) Speedometer illumination
 b) Revolution counter illumination
 c) Brake fluid level telltale tred)
 d) Neutral indicator (green)
 e) Charge indicator (red)
 f) Oil pressure telltale (cranae)
 g) Turn indicator repeater (green)
 h) Headlight high beam indicator (blue)


 13 Brake pedal stoplight switch
 14 Starter relay
 15 Relay
 16 Ignition coils
 17 Spark plugs with caps
 18 Condenser
 19 Contact breaker
 20 Starter
 21 Battery

- 20 Starter 21 Battery 22 Alternator 23 Voltage regulator 24 Diode board 25 Plug, 1-pole 26 Plug, 2-pole 27 Buzzer 28 Blue, 5-pole



1

NS.



Return to Technical Articles Index Page

Return to HomePage